

## Activate a single user license for LensMechanix

LensMechanix is an annual subscription license. It must be installed on your computer, and you must have a valid LensMechanix user license to activate it. LensMechanix does not require an OpticStudio license.

1. After you download and install LensMechanix, click **Start** in the Windows taskbar and search for the **Zemax License Manager**.
2. Double-click **Zemax License Manager** to open it.
3. In the Zemax License Manager dialog box, click **New key**.
4. In the field that appears, copy and paste the activation code you received by email.
5. Click **Apply License**.
6. Click **License Information**.
7. Verify that your key serial number, key ID, and support expiration date appear.
8. To complete the activation process, open your CAD platform (SOLIDWORKS 2016, 2017, or 2018, or Creo Parametric 4.0).

Wait while the program files are copied to your My Documents folder.

LensMechanix displays in the SOLIDWORKS Command Manager and the Creo Ribbon.